

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

FU867  
WSW  
> 1  
1.170 mi.  
6176 ft.

NYC HOUSING AUTHORITY  
2951 WEST 33RD ST  
BROOKLYN, NY

NY Spills S116155705  
N/A

Site 1 of 4 in cluster FU

Relative:  
Higher

Actual:  
8 ft.

SPILLS:

Name: NYC HOUSING AUTHORITY  
Address: 2951 WEST 33RD ST  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 1309420 / 2014-10-07  
Facility ID: 1309420  
Facility Type: ER  
DER Facility ID: 445286  
Site ID: 490217  
DEC Region: 2  
Spill Cause: Equipment Failure  
  
Spill Class: Not reported  
SWIS: 2401  
Spill Date: 2013-12-24  
Investigator: SXMAHAT  
Referred To: Not reported  
Reported to Dept: 2013-12-24  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2013-12-24  
Spill Record Last Update: 2015-10-28  
Spiller Name: Not reported  
Spiller Company: CONTRACTOR CALLED WARE  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: YELENA TKACH  
DEC Memo: "8/18/14: Mahat DEC Mahat contacted Notifier ( Yelana @ 917.518.6355 ) regarding the clean up report. She mentioned that the site has been clean and the clean up report will be submitted to the Department in first week of Septmenber. 10/7/14 : Mahat DEC Mahat received an report from Ms. Yelana with manifest and clean up narrative report. It is uploaded on D2 for reference. Based on the doucuments provided, spill was all conatined in the concrete and clean up has been performed. Further investigation on remediation and deliniation is not required by the Department. Hence, the spill case will be closed in the database. "

Remarks: "cleanup in progress"

All Materials:

Site ID: 490217  
Operable Unit ID: 1239781  
Operable Unit: 01  
Material ID: 2239843  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material FA:	Petroleum
Quantity:	45.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported